



34400 Mound Rd. Sterling Heights, MI 48310

1-844-VSE-RUST (1-844-873-7878)

E-mail: 1844VSE-RUST@VSECORP.COM

Corrosion Prevention Material Case History Corrosion Repair and Protection: Hawaii National Guard Equipment Storage

DATE: August 2009



PROBLEM: The Hawaii National Guard was going to be deployed without their equipment. They needed a method to store their equipment since there was not going to be a rear detachment to care for it during the deployment period.

APPLICATION: All of the equipment was serviced by the VSE Corrosion Prevention and Control (CPAC) Team which included cleaning, corrosion repair/repaint, and application of a corrosion prevention compound (cpc). The equipment was then put into a special corrosion prevention enclosure, similar to shrink wrap but with a special material lining the inside, to be stored for the duration of the deployment.

SOLUTION: The equipment, having been properly prepared and put into storage, was retrieved at the end of the deployment period in an excellent condition. These environmentally friendly products and processes have provided an easy, cost effective solution to help maintain this customer's needs.

1-844-VSE-RUST (1-844-873-7878)

1-586-254-8983

WWW.VSECORP.COM

CORROSIONCONQUERED.COM